



UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
P.O. Box 1450
Alexandria, VA 22313-1450

September 9, 2006

**ECKERT SEAMANS CHERIN & MELLOTT
600 GRANT STREET
44TH FLOOR
PITTSBURGH PA 15219**

Patent No. : 7,048,779 B1
Inventor(s) : Thomas Weyand, et al.
Issued : May 23, 2006
For : **METHOD OF REMOVING MERCURY
FROM EXHAUST GASES OF COAL FIRED
POWER PLANTS AND ASSOCIATED
APPARATUS**
Doc. No. 164319-00027

To Whom It May Concern:

The Certificate of Correction issued on August 29, 2006, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The application number in the heading of cofc has been incorrectly entered on issued cofc by the PTO. A superseding cofc will be issued to correct the application number to read as -- 09/720,589--.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson
(703) 308-9390 ext. 111
For Cecelia Newman, Supervisor
Decisions & Certificates of Correction Branch
(703) 305-8309 / 703-308-9390 ext. 102
cbn